American Honda Motor Co., Inc.

SAFETY RECALL NOTICE

Honda GCV160LA0 R3A ENGINE installed on COLUMBIA ELECTRIC START LAWN MOWERS



Engine Model	Affected Serial Number Range	Columbia Model	Affected Serial Number Range
GCV160LA0R3A	GJARA-3641197 ~ GJARA-3642215	12ALD33Q897	1A313KC0835 ~ 1A313KC0992

What is the problem?

- The engine stop switch may become inoperative allowing the lawn mower engine to continue to run after the blade control lever is released
- Because the blade continues to rotate, this poses a potential safety hazard to the operator or a bystander

What should you do?

- Check to see if the lawn mower model and engine serial number are within the affected range
- Do not use the lawn mower until it has been repaired
- Contact an authorized Honda Power Equipment servicing dealer to make an appointment to have the engine flywheel brake assembly replaced free of charge

Affected units that have already been repaired are no longer part of this recall.

Repaired units can be identified by a punch mark next to the engine serial number.



If you need assistance locating an authorized Honda Power Equipment servicing dealer: Website: www.powerequipment.honda.com Phone: (888) 888-3139.

This recall is being conducted in cooperation with the U.S. Consumer Product Safety Commission.