

American Honda Motor Co., Inc.


SAFETY AND EMISSIONS

RECALL NOTICE

HUSKEE & SPLIT MASTER LOG SPLITTERS CRACKED FUEL TANK

Check below to see if your Log Splitter is affected by this recall.

HUSKEE & SPLIT MASTER LOG SPLITTERS



Huskee Models

LS401227TS (22 Ton)
LS401228NO (27 Ton)

Split Master Models

LS401227SP (22 Ton)
LS401227NO (22 Ton)
LS401225NO (25 Ton)

Affected Honda Engine Serial Numbers

GJAEA - 5547012 ~ 6880908

⚠ WARNING

Gasoline is highly flammable and explosive. You can be burned or seriously injured if gasoline from a leaking fuel tank is ignited. If the fuel tank is leaking:

- Move the log splitter outside and away from any source of ignition.
- Do not use your log splitter until it has been repaired.

Consumers should immediately stop using the recalled log splitters and contact a Honda Power Equipment dealer for a free repair.

What is the problem?

Due to a manufacturing defect, over time, a crack may form in the fuel tank mounting tab causing a fuel leak. This problem is application specific, other (non-listed) engines are not included in this recall.

What should you do?

Consumers should immediately stop using their affected log splitter until the fuel tank has been replaced. If you need assistance, please see a member of this dealership's staff or any authorized Split Master, Huskee or Honda servicing dealer for assistance. If you need additional assistance that this dealer is unable to provide, you may contact American Honda Customer Relations at 1-888-888-3139 or Special Products Co. at 1-877-832-7639.

In cooperation with the U.S. Consumer Product Safety Commission and California Air Resources Board