

American Honda Motor Co., Inc.

EMISSIONS RECALL NOTICE

GX630R • GX660R • GX690R • GX690
GXV630R • GXV660R • GXV690R

IGNITION COILS

Check below to see if your engine is affected by this recall.

MODEL	START SERIAL NUMBER	END SERIAL NUMBER
GX630R	GCBEK-1057259	GCBEK-1063705
GX660R	GCBFK-1007293	GCBFK-1007993
GX690R	GCBGK-1020163	GCBGK-1023184
GX690	GDACK-1000260	GDACK-1000451
GXV630R	GJANK-1003116	GJANK-1003415
GXV660R	GJAPK-1002337	GJAPK-1002624
GXV690R	GJARK-1000606	GJARK-1000941



Consumers should stop using their Honda-powered equipment and contact a Honda Engine dealer for a free repair.

What is the problem?

The engine may have an ignition coil malfunction, causing the engine to run on one cylinder. The engine may appear to run, but when a heavy load is applied, the engine may stop running.

What should you do?

Stop using your Honda powered equipment and contact a servicing Honda Engine dealer to make an appointment to have the ignition coils inspected and, if necessary, replaced free of charge. Transportation of the equipment to the dealer is the responsibility of the owner. If you need assistance locating a servicing Honda Engine dealer, please visit our web site: www.engines.honda.com. or contact us at (888) 888-3139.

In cooperation with the U.S. Environmental Protection Agency and the California Air Resources Board