

American Honda Motor Co., Inc.

SAFETY AND EMISSIONS **RECALL NOTICE**

BF2.3DK2 PORTABLE OUTBOARD MOTOR GAS CAP VENT LEAK

Check below to see if your outboard is affected by this recall.

AFFECTED UNITS

Start Frame Serial Number	End Frame Serial Number
BAVJ-2300008	BAVJ-2312793

What is the problem?

Units within the affected serial number range have a defect that can result in the gas cap vent gasket becoming misaligned. If the gas cap vent gasket becomes misaligned, gas can leak from the cap when its vent knob is in the OFF position and the outboard motor is placed on its side (horizontally).

What should you do?

If you own a BF2.3DK2 outboard motor shown here, you will need to check to see if the serial number is within the affected serial number range. If it is within the affected range and:

- If your outboard motor was registered with American Honda, you will receive a letter with a new updated gas cap.
- If your outboard motor was not registered with American Honda, contact your Honda Marine servicing dealer for a free replacement gas cap.
- If you transport or store your outboard motor horizontally and have yet to install an updated gas cap, drain all the gas from the gas tank before placing the outboard motor on its side.

If you need assistance locating a servicing dealer, please visit our website: www.marine.honda.com, or contact us at (888) 888-3139.

Gas may leak from the gas cap vent.



Serial number location

In cooperation with the U.S. Coast Guard and the
Environmental Protection Agency