

PRODUCT SAFETY RECALL
Main Engine Wiring Harness
Issued May 2003

MODEL: Honda Marine BF200 and BF225 outboard motors.

SERIAL #'s BAEJ-1000001-1199999 (BF200)
BAGJ-1000001-1199999 (BF225)

PROBLEM: The routing of the engine wiring harness may allow contact with the throttle body under normal running conditions. Eventually, the repeated contact may wear thru the wires insulation and cause a short circuit. This may cause a blown fuse (15A) and the engine will stop or the short may cause the throttle cable to overheat and become difficult to move or, in the worst case, the throttle could become stuck.

* If you have experienced a blown 15 amp fuse we strongly recommend that you stop using the outboard motor until it has been inspected

WHAT TO DO: Please contact a servicing Honda marine dealer to have your motor inspected. You may contact a local Honda authorized dealer in your area. To find the nearest Honda authorized dealer you may check our web site: www.honda-marine.com or call toll free 1-888-888-3139 for the dealer locator.