

PRODUCT SAFETY RECALL
Clutch Rod
Revised November 1995

- MODEL:** H1011 Honda Riding Mowers non hydrostatic units shipped before February 1, 1995
- PROBLEM:** On a limited number of riding mowers, Clutch Rod A, the front half of the clutch rod assembly, may break at the bend where it attaches to the clutch pedal. Should this happen, the operator will not be able to disengage power to the rear wheels with the clutch pedal. Depending on conditions, using the foot brake may not bring the mower to a stop, unless the operator shuts off the engine.
- WHAT TO DO:** Please contact a servicing Honda lawn and garden dealer to make an appointment to have your riding mower repaired. To find the nearest Honda authorized dealer you may check our dealer locator on our web site: www.hondapowerequipment.com or call toll free 1-888-888-3139.