

American Honda Motor Co., Inc.

PRODUCT UPDATE NOTICE

BF200D • BF225D • BF250D Outboards

COOLING SYSTEM INDICATOR

Check the list of affected serial numbers to see if your outboard is affected by this product update.

What is the problem?

Water may not be flowing out of the cooling system indicator while the engine is running and/or water is seen leaking from the outboard between the engine cover and lower covers.

This condition can damage certain engine components such as the fuel pump, ignition coils, or starter motor, and cause the outboard to not start or operate properly.

Affected Serial Numbers:

If your frame serial number is listed within the ranges below, your outboard is affected by this product update.

MODEL	ROTATION	SERIAL NUMBER RANGE
BF200D	Standard	BBRJ-1000001 ~ 1011476
BF200D	Counter	BBRJ-8000001 ~ 8010193
BF225D	Standard	BBPJ-1000001 ~ 1011187
BF225D	Counter	BBPJ-8000001 ~ 8010561
BF250D	Standard	BBNJ-1000001 ~ 1013580
BF250D	Counter	BBNJ-8000001 ~ 8010972

What should you do?

Please contact your Honda Marine servicing dealer to make arrangements to have your BF200D, BF225D, or BF250D repaired. The dealer will install a metal retaining clip onto a rubber hose in the cooling system indicator, and if required, perform a multi-point inspection at no charge to you. Transportation of the outboard to the dealer is the responsibility of the owner.

If you need assistance locating a servicing Honda Marine dealer, please visit our website: marine.honda.com or you can contact American Honda at:

America Honda Motor Co., Inc.

Marine Group

Customer Relations Office

4900 Marconi Drive

Alpharetta, GA 30005-8847

Telephone (888) 888-3139 tollfree or local (770) 497-6400

M-F 9:00 am - 7:30 pm (Easter Time Zone)



COOLING SYSTEM INDICATOR

A steady stream of water should flow out of the indicator hole when the outboard is running.

SERIAL NUMBER

The serial number can be found on the left-hand side of the transom mounting bracket.