

American Honda Motor Co., Inc.

SAFETY RECALL NOTICE

Honda Marine **EMERGENCY STOP SWITCH CLIP**

Check below to see if your motor is affected by this recall.

Honda Marine Motors BF2D ~ BF225A

AFFECTED UNITS

Model	Frame Serial Number Range
BF2D	BZBF-2314503 ~ 2314878
BF5A	BADS-2305425 ~ 2305566
BF(P)8D	BAAJ-1603522 ~ 1603608
BF(P)9.9D	BABJ-1608499 ~ 1608644
BF15D	BALJ-1405681 ~ 1405782
BF20D	BAMJ-1408244 ~ 1408354
BF25D	BATJ-1301923 ~ 1301938
BF30D	BAUJ-1302598 ~ 1302686
BF40D	BBDJ-1006633 ~ 1007003
BF50D	BBEJ-1013317 ~ 1014021
BF60A	BBFJ-1003087 ~ 1003326
BFP60A	BBFJ-8000655 ~ 8000720
BF75D	BBAJ-1006096 ~ 1006367
BF90D	BBCJ-1019128 ~ 1019981
BF200A	BAFJ-1600066 ~ 1600074 BAEJ-1600439 ~ 1600519
BF225A	BAHJ-1600722 ~ 1600762 BAGJ-1602167 ~ 1602369

A crack may develop in this area.



What is the problem?

Due to an error in manufacturing, a crack may develop in the inner radius of the emergency stop switch clip. If the crack goes unnoticed, the clip could fall off during operation, causing the engine to shut off unexpectedly.

All clips provided with the affected engines are included in this recall.

What should you do?

Contact your Honda Marine servicing dealer for a replacement emergency stop switch clip. If you need assistance locating a servicing dealer, please visit our website: www.honda-marine.com, or contact us at (888) 888-3139.

In cooperation with the U.S. Coast Guard