

# **SAFETY RECALL NOTICE**

## **Honda Marine BF200D • BF225D • BF250D Broken Shift Actuator Link Rod**

Check below to see if your Honda outboard motor is affected by this recall.

### **Affected Units:**

This recall only applies to drive-by-wire (DBW) equipped models with serial numbers in the table below.

<b>Model</b>	<b>Gear Case</b>	<b>Frame Serial Number Range</b>
BF200D	Standard	BBRJ-1010380 ~ BBRJ-1015617
	Counter-rotating	BBRJ-8010059 ~ BBRJ-8011269
BF225D	Standard	BBPJ-1010286 ~ BBPJ-1014399
	Counter-rotating	BBPJ-8010176 ~ BBPJ-8012350
BF250D	Standard	BBNJ-1010708 ~ BBNJ-1023456
	Counter-rotating	BBNJ-8010148 ~ BBNJ-8014544



### **What is the problem?**

The actuator link rod in the DBW shifting system may break during use, causing a loss of shift operation and the potential loss of control of the vessel, increasing the risk of a crash or injury.

The operator will notice the failure when attempting to shift into a different gear and the boat continues moving in the same direction as the last shift position.

### **What should you do?**

If you own a Honda BF200D, BF225D, or BF250D outboard motor equipped with DBW, you will need to check to see if the frame serial number is within the affected serial number ranges shown above. If it is within the affected ranges, do not use the outboard until it is repaired and:

- If your outboard motor was registered with American Honda, you will receive a letter.
- If your outboard motor was not registered with American Honda, contact your Honda Marine servicing dealer.

If you need assistance locating a servicing dealer, please visit our website:

[www.marine.honda.com](http://www.marine.honda.com), or contact us at (888) 888-3139 between the hours of 9:00 a.m. - 7:30 p.m. ET

In cooperation with the U.S. Coast Guard