American Honda Motor Co., Inc.

PRODUCT UPDATE NOTICE

BF200D • BF225D • BF250D Outboards COOLING SYSTEM WATER TUBE

Check the list of affected serial numbers to see if your outboard is affected by this product update.

What is the problem?

A cooling system water return tube can rupture and allow water to enter the engine compartment. If this happens, water may be seen leaking from the outboard between the engine cover and lower covers, water is found inside the engine compartment, or water marking is found on engine components.

This condition can damage certain engine components such as the fuel pump, ignition coils, or starter motor, and cause the outboard to not start or operate properly.

Affected Serial Numbers:

If your frame serial number is listed within the ranges below, your outboard is affected by this product update.

MODEL	ROTATION	SERIAL NUMBER RANGE
BF200D	Standard	BBRJ-1000001 ~ BBRJ-1013729
	Counter	BBRJ-8000001 ~ BBRJ-8011053
BF225D	Standard	BBPJ-1000001 ~ BBPJ-1013424
	Counter	BBPJ-8000001 ~ BBPJ-8012093
BF250D	Standard	BBNJ-1000001 ~ BBNJ-1018616
	Counter	BBNJ-8000001 ~ BBNJ-8013300

What should you do?

Please contact your Honda Marine servicing dealer to make arrangements to have your BF200D, BF225D, or BF250D repaired. The dealer will install a revised rubber water tube and tube clamps in the cooling system, and if required, perform a multi-point inspection at no charge to you.

Transportation of the outboard to the dealer is the responsibility of the owner.

If you need assistance locating a servicing Honda Marine dealer, please visit our website: marine.honda.com or you can contact American Honda at:

America Honda Motor Co., Inc. Marine Group Customer Relations Office 4900 Marconi Drive Alpharetta, GA 30005-8847 Telephone (888) 888-3139 toll free or local (770) 497-6400 M-F 9:00 am - 7:30 pm (Easter Time Zone)







Post in a prominent location until November 30th, 2022