

# SAFETY AND EMISSIONS RECALL NOTICE

## EU7000isAN Generator DEFECTIVE FUEL FILLER CAP

Check below to see if your generator is affected by this recall.




Open the right-side maintenance cover. The frame serial number is located on the shroud below the recoil starter grip.

Refer to the frame serial number list shown to the right for the individual units affected by this recall.

If you are unsure if your generator is affected by this recall, contact your local authorized Honda servicing dealer, or call the Honda recall line at (888) 888-3139 for assistance.

Units previously inspected/repared are no longer part of this recall.

They can be identified as follows:



A white paint mark on the underside of the fuel filler cap.

OR

A "7FB" label located inside the cover by the frame serial number.



Only the frame serial numbers listed below are affected by this recall:

EEJD-1364963	EEJD-1365040	EEJD-1365318	EEJD-1365921	EEJD-1365980
EEJD-1364964	EEJD-1365041	EEJD-1365319	EEJD-1365922	EEJD-1365981
EEJD-1364965	EEJD-1365042	EEJD-1365320	EEJD-1365923	EEJD-1365982
EEJD-1364966	EEJD-1365043	EEJD-1365682	EEJD-1365924	EEJD-1365983
EEJD-1364967	EEJD-1365044	EEJD-1365683	EEJD-1365925	EEJD-1365984
EEJD-1364968	EEJD-1365045	EEJD-1365684	EEJD-1365926	EEJD-1365985
EEJD-1364971	EEJD-1365046	EEJD-1365685	EEJD-1365927	EEJD-1365986
EEJD-1364972	EEJD-1365047	EEJD-1365686	EEJD-1365928	EEJD-1365987
EEJD-1364973	EEJD-1365048	EEJD-1365687	EEJD-1365929	EEJD-1365988
EEJD-1364974	EEJD-1365049	EEJD-1365688	EEJD-1365930	EEJD-1365989
EEJD-1364975	EEJD-1365050	EEJD-1365689	EEJD-1365931	EEJD-1365990
EEJD-1364976	EEJD-1365051	EEJD-1365690	EEJD-1365932	EEJD-1365991
EEJD-1364979	EEJD-1365052	EEJD-1365691	EEJD-1365933	EEJD-1365992
EEJD-1364980	EEJD-1365053	EEJD-1365692	EEJD-1365934	EEJD-1365993
EEJD-1364997	EEJD-1365054	EEJD-1365693	EEJD-1365935	EEJD-1365994
EEJD-1365001	EEJD-1365055	EEJD-1365694	EEJD-1365936	EEJD-1365995
EEJD-1365002	EEJD-1365056	EEJD-1365695	EEJD-1365937	EEJD-1365996
EEJD-1365003	EEJD-1365057	EEJD-1365857	EEJD-1365938	EEJD-1365997
EEJD-1365004	EEJD-1365058	EEJD-1365858	EEJD-1365939	EEJD-1365998
EEJD-1365005	EEJD-1365059	EEJD-1365875	EEJD-1365940	EEJD-1365999
EEJD-1365006	EEJD-1365060	EEJD-1365876	EEJD-1365941	EEJD-1366000
EEJD-1365009	EEJD-1365061	EEJD-1365877	EEJD-1365942	EEJD-1366001
EEJD-1365010	EEJD-1365062	EEJD-1365878	EEJD-1365943	EEJD-1366002
EEJD-1365011	EEJD-1365063	EEJD-1365881	EEJD-1365944	EEJD-1366003
EEJD-1365012	EEJD-1365066	EEJD-1365882	EEJD-1365945	EEJD-1366004
EEJD-1365013	EEJD-1365067	EEJD-1365883	EEJD-1365946	EEJD-1366005
EEJD-1365014	EEJD-1365070	EEJD-1365884	EEJD-1365949	EEJD-1366006
EEJD-1365015	EEJD-1365071	EEJD-1365885	EEJD-1365950	EEJD-1366007
EEJD-1365017	EEJD-1365072	EEJD-1365886	EEJD-1365951	EEJD-1366008
EEJD-1365018	EEJD-1365073	EEJD-1365887	EEJD-1365952	EEJD-1366009
EEJD-1365019	EEJD-1365074	EEJD-1365888	EEJD-1365953	EEJD-1366010
EEJD-1365020	EEJD-1365075	EEJD-1365889	EEJD-1365954	EEJD-1366011
EEJD-1365021	EEJD-1365076	EEJD-1365890	EEJD-1365955	EEJD-1366012
EEJD-1365022	EEJD-1365077	EEJD-1365891	EEJD-1365956	EEJD-1366013
EEJD-1365023	EEJD-1365078	EEJD-1365892	EEJD-1365957	EEJD-1366014
EEJD-1365024	EEJD-1365079	EEJD-1365893	EEJD-1365958	EEJD-1366015
EEJD-1365025	EEJD-1365090	EEJD-1365894	EEJD-1365963	EEJD-1366016
EEJD-1365026	EEJD-1365091	EEJD-1365895	EEJD-1365964	EEJD-1366017
EEJD-1365027	EEJD-1365092	EEJD-1365896	EEJD-1365965	EEJD-1366018
EEJD-1365028	EEJD-1365093	EEJD-1365909	EEJD-1365966	EEJD-1366019
EEJD-1365029	EEJD-1365094	EEJD-1365910	EEJD-1365967	EEJD-1366020
EEJD-1365030	EEJD-1365095	EEJD-1365911	EEJD-1365968	EEJD-1366021
EEJD-1365031	EEJD-1365096	EEJD-1365912	EEJD-1365971	EEJD-1366022
EEJD-1365032	EEJD-1365097	EEJD-1365913	EEJD-1365972	EEJD-1366023
EEJD-1365033	EEJD-1365102	EEJD-1365914	EEJD-1365973	EEJD-1366024
EEJD-1365034	EEJD-1365103	EEJD-1365915	EEJD-1365974	EEJD-1366025
EEJD-1365035	EEJD-1365122	EEJD-1365916	EEJD-1365975	EEJD-1366026
EEJD-1365036	EEJD-1365123	EEJD-1365917	EEJD-1365976	
EEJD-1365037	EEJD-1365134	EEJD-1365918	EEJD-1365977	
EEJD-1365038	EEJD-1365135	EEJD-1365919	EEJD-1365978	
EEJD-1365039	EEJD-1365317	EEJD-1365920	EEJD-1365979	

### What is the problem?

Due to a manufacturing defect, the outer metal cover of the fuel filler cap may separate from the rest of the fuel filler cap during use.

As a result, fuel and/or fuel vapor may leak during or after operation, posing a fire hazard.

### What should you do?

If you own an EU7000isAN generator, you will need to check to see if the serial number is within the affected serial number range and has not been previously repaired. If it is within the affected range and has not been previously repaired, stop using your generator until it has been repaired by an authorized Honda dealer. Also:

- If your generator was registered with American Honda and is affected, you will receive a letter.
- If your generator was not registered with American Honda, contact your Honda Power Equipment servicing dealer.

If you need assistance locating a servicing dealer, please visit our website: [www.PowerEquipment.Honda.com](http://www.PowerEquipment.Honda.com), or call us at our toll free recall line (888) 888-3139.

This recall is being conducted in cooperation with the U.S. Consumer Product Safety Commission