

American Honda Motor Co., Inc.

# **SAFETY AND EMISSIONS** **RECALL NOTICE**

## **BILLY GOAT<sup>®</sup> MV MULTIVAC** **CRACKED FUEL TANK**

Check below to see if your outdoor vacuum is affected by this recall.

### **MV MULTIVAC**



#### **Billy Goat Affected Serial Numbers**

061107xxx	072407xxx	082007xxx
061807xxx	073007xxx	082707xxx
062507xxx	080607xxx	090407xxx
070907xxx	081307xxx	091007xxx

#### **⚠ WARNING**

Gasoline is highly flammable and explosive. You can be burned or seriously injured if gasoline from a leaking fuel tank is ignited. If the fuel tank is leaking:

- Move the outdoor vacuum away from any source of ignition.
- Drain the fuel tank into an approved container.
- Do not use your outdoor vacuum until it has been repaired.

**If your model is included in this recall, WE STRONGLY RECOMMEND NOT USING IT.**

#### ***What is the problem?***

Due to a manufacturing defect, over time, a crack may form in the fuel tank mounting tab causing a fuel leak.

#### ***What should you do?***

We strongly recommend that you stop using your outdoor vacuum until the fuel tank has been replaced. If you need assistance, please see a member of this dealership's staff or any authorized Billy Goat or Honda servicing dealer for assistance. If you need additional assistance that this dealer is unable to provide, you may contact American Honda Customer Relations at (770) 497-6400 or Billy Goat Industries at (816) 524-9666.

In cooperation with the Consumer Product Safety Commission and California Air Resources Board

PTB54004 (2007.11)