

American Honda Motor Co., Inc.

PRODUCT UPDATE NOTICE

BF200AK3 • BF225AK3 • BF250A Outboards

LEFT TIMING BELT DRIVEN PULLEY REPLACEMENT

Check the list of affected serial numbers to see if your outboard is affected by this product update.

What is the problem?

The left timing belt driven pulley may interfere with and damage the TDC sensor due to improper riveting on the pulley's sensor pick-up plate.

If the left timing belt driven pulley fails, the warning system buzzer on the outboard motor will sound and the engine will shut off and cannot be restarted.



Affected Serial Numbers:

Click [here](#) to find out if your outboard is affected by this product update.

What should you do?

Please contact your Honda Marine servicing dealer to make arrangements to have your BF200AK3, BF225AK3, or BF250A repaired. The dealer will replace the timing belt pulley and, if needed, the TDC sensor at no charge to you while the outboard is still under warranty. Transportation of the outboard to the dealer is the responsibility of the owner.

If you need assistance locating a servicing Honda Marine dealer, please visit our website: marine.honda.com or call our customer service line at (770) 497-6400.



Affected Serial Numbers

If your frame serial number is listed below, your outboard is affected by this product update.

MODEL	FRAME SERIAL NUMBER					
BF200AK3	BAEJ-1800123	BAEJ-1800124	BAEJ-1800125	BAEJ-1800126	BAEJ-1800127	BAEJ-1800128

BF225AK3	BAHJ-1800183	BAGJ-1800376	BAGJ-1800380	BAGJ-1800422	BAGJ-1800431	BAGJ-1800437
	BAHJ-1800184	BAGJ-1800377	BAGJ-1800383	BAGJ-1800427	BAGJ-1800432	BAGJ-1800447
	BAHJ-1800185	BAGJ-1800378	BAGJ-1800384	BAGJ-1800428	BAGJ-1800434	BAGJ-1800448
	BAHJ-1800186	BAGJ-1800379	BAGJ-1800385	BAGJ-1800429	BAGJ-1800436	BAGJ-1800450
	BAHJ-1800188					

BF250A	BBJJ-1002343	BBJJ-1002356	BBJJ-1002371	BBJJ-1002385	BBJJ-1002476	BBJJ-1002538
	BBJJ-1002344	BBJJ-1002357	BBJJ-1002372	BBJJ-1002386	BBJJ-1002477	BBJJ-1002539
	BBJJ-1002345	BBJJ-1002358	BBJJ-1002373	BBJJ-1002387	BBJJ-1002478	BBJJ-1002540
	BBJJ-1002346	BBJJ-1002359	BBJJ-1002376	BBJJ-1002388	BBJJ-1002479	BBJJ-1002543
	BBJJ-1002347	BBJJ-1002360	BBJJ-1002377	BBJJ-1002389	BBJJ-1002480	BBJJ-1002544
	BBJJ-1002348	BBJJ-1002361	BBJJ-1002378	BBJJ-1002469	BBJJ-1002481	BBJJ-1002545
	BBJJ-1002349	BBJJ-1002362	BBJJ-1002379	BBJJ-1002470	BBJJ-1002482	BBJJ-1002546
	BBJJ-1002350	BBJJ-1002363	BBJJ-1002380	BBJJ-1002471	BBJJ-1002483	BBJJ-8000625
	BBJJ-1002351	BBJJ-1002364	BBJJ-1002381	BBJJ-1002472	BBJJ-1002484	BBJJ-8000630
	BBJJ-1002352	BBJJ-1002365	BBJJ-1002382	BBJJ-1002473	BBJJ-1002535	BBJJ-8000631
	BBJJ-1002353	BBJJ-1002366	BBJJ-1002383	BBJJ-1002474	BBJJ-1002536	BBJJ-8000632
	BBJJ-1002355	BBJJ-1002370	BBJJ-1002384	BBJJ-1002475	BBJJ-1002537	

Click [here](#) to return to the Product Update Notice.