# PRODUCT UPDATE NOTICE

### Honda Marine

# INCORRECT DATE ON EMISSION CONTROL SYSTEM WARRANTY STATEMENT

## What is the problem?

The *Emission Control System Warranty Statement* in the Owner's Manual displays the incorrect outboard model years (2013-2014) and does not agree with the emission label date of 2015 or 2016. This typographical error concerning the applicable model years does not affect your warranty rights and obligations in any way.

ENGINE FAMILY-FHNXM	FORMATION-HONDA MOTOR CO., LTD. J. 3502G0, DISPLACEMENT-0.350 liters. /ER-BF20D : 14.9kW, BF15D / BFP15D : 11.2kW	HONDA
FEL-HC+NOx:20.00g/k	/ER-BF20D:14.9kW, BF15D/BFP15D:11.2kW N-hr. NS (READ OWNER'S MANUAL FOR MORE DETAILS)	EM
	900 ± 50 r.p.m. AT NORMAL OPERATING TEMPERATU	RE
VALVE LASH (COLD)	IN:0.17 ± 0.02mm, EX:0.23 ± 0.02mm	/
FUEL	UNLEADED GASOLINE 86 PUMP OCTANE OR HIGHER	
SPARK PLUG & GAP	PLUG TYPE:NGK CR5EH-9, DENSO U16FER9 OR FOO	VALENT 0.8-0.9mm
THIS ENGINE MEETS U.	5. EPA EXH AND CALIFORNIA EMISSION REGS FOR 20	015.
THE ENGINE MEETS O.	S. ELA EXITAND GALIFORNIA EMISSION REGS FIR 20	

EMISSION LABEL DATE

Model	Starting Serial Number	Ending Serial Number	Model	Starting Serial Number	Ending Serial Number
BF2.3DH	BABC-1002259	BABC-1007745	BF90DK4	BBCJ-1301359	BBCJ-1302807
BF2.3DK2	BAVJ-2330869	BAVJ-2337512	BF100A	BBMJ-1002750	BBMJ-1003164
BF5AK3	BADS-2502148	BADS-2503043	BF115DK1 (standard)	BBHJ-1102883	BBHJ-1103809
BF/BFP8DK3	BAAJ-1801639	BAAJ-1802092	BF115DK1 (counter)	BBHJ-8100082	BBHJ-8100096
BF/BFP9.9DK3	BABJ-1804573	BABJ-1806047	BF135AK2 (standard)	BARJ-1401260	BARJ-1401655
BF/BFP15DK3	BALJ-1602198	BALJ-1603091	BF135AK2 (counter)	BASJ-1400164	BASJ-1400203
BF20DK3	BAMJ-1603320	BAMJ-1604527	BF150AK2 (standard)	BANJ-1405197	BANJ-1406824
BF25DK3	BATJ-1500515	BATJ-1500718	BF150AK2 (counter)	BAPJ-1400603	BAPJ-1400772
BF30DK3	BAUJ-1500845	BAUJ-1501190	BF200AK3 (standard)	BAEJ-1800403	BAEJ-1800827
BF40DK2	BBDJ-1104391	BBDJ-1105702	BF200AK3 (counter)	BAFJ-1800053	BAFJ-1800081
BF50DK2	BBEJ-1109374	BBEJ-1112820	BF225AK3 (standard)	BAGJ-1800902	BAGJ-1801454
BF60AK1	BBFJ-1103802	BBFJ-1105528	BF225AK3 (counter)	BAHJ-1800352	BAHJ-1800618
BFP60AK1	BBFJ-8100932	BBFJ-8101328	BF250A (standard)	BBJJ-1003738	BBJJ-1005101
BF75DK3	BBAJ-1200176	BBAJ-1200439	BF250A (counter)	BBJJ-8000912	BBJJ-8001304

#### AFFECTED UNITS (Units sold or placed into service in the state of California)

# What should you do?

Affected customers residing in California have been mailed a revised *Emission Control System Warranty Statement.* If you have not received a revised statement and believe you own an affected unit, you can visit the Honda Marine website to download the corrected statement, or you can contact American Honda at:

#### American Honda Motor Co., Inc.

Marine Group Customer Relations Office 4900 Marconi Drive Alpharetta, GA 30005-8847 Telephone (770) 497-6400 M-F 8:30 am-7:00 pm (Eastern Time Zone)

#### In cooperation with the California Air Resources Board

Post in a prominent location from May 26, 2016, through September 26, 2016