

American Honda Motor Co., Inc.

SAFETY RECALL NOTICE

HRB217HXA • HRX217HXA • HRX217HMA Lawn Mowers

BROKEN ROTO-STOP[®] RETURN SPRING

Check below to see if your lawn mower is affected by this recall.

**HRB217HXA • HRX217HXA
HRX217HMA**

Affected Serial Numbers

MAEA - ALL

MAGA - 1000001 ~ 1513628

HRB217HXA



SERIAL NUMBER LOCATION

MEETS CPSC BLADE SAFETY
REQUIREMENTS.
MODEL: HRB217HXA AG
SERIAL NO: MAEA-1XXXXXX
AMERICAN HONDA MOTOR CO., INC.
ALPHARETTA, GA 30005-8847

⚠ WARNING

The Roto-Stop return spring on your lawn mower may break without warning. The brake mechanism will no longer operate, the clutch will remain engaged, and the cutting blades will rotate under power after the blade control lever is released.

If the cutting blades continue to rotate after the blade control lever is released, the spinning blades pose a serious laceration hazard.

Stop using your lawn mower until the Roto-Stop return spring has been replaced.



HRX217HMA

What is the problem?

The Roto-Stop return spring on affected lawn mowers could break at the hook end. When this occurs, the Roto-Stop brake mechanism no longer operates, the clutch remains engaged, and the cutting blades rotate under power after the blade control lever is released.

What should you do?

Stop using your lawn mower until the Roto-Stop return spring has been replaced. Please contact a servicing Honda Power Equipment dealer to make an appointment to have your HRB217HXA, HRX217HXA, or HRX217HMA lawn mower repaired. The dealer will replace the Roto-Stop return spring, free of charge. Transportation of the lawn mower to and from the dealer is the responsibility of the owner.

If you need assistance locating a servicing Honda Power Equipment dealer, please visit our website: www.hondapowerequipment.com, or contact us at (888) 888-3139.

In cooperation with the Consumer Product Safety Commission.