

American Honda Motor Co., Inc.

SAFETY AND EMISSIONS RECALL NOTICE

HRX217KHXA • HRX217KHMA Lawn Mowers CRACKED FUEL TANK

Check below to see if your lawn mower is affected by this recall.

HRX217KHXA • HRX217KHMA



(HRX217KHXA shown)

Affected Serial Numbers

MAGA - 1400001 ~ 1453724

⚠ WARNING

Gasoline is highly flammable and explosive. You can be burned or seriously injured if gasoline from a leaking fuel tank is ignited. If the fuel tank is leaking:

- Move the lawn mower away from any source of ignition.
- Drain the fuel tank into an approved container.
- Do not use your lawn mower until it has been repaired.

If your model is included in this recall, WE STRONGLY RECOMMEND NOT USING IT.

What is the problem?

Due to a manufacturing defect, over time, a crack may form in the fuel tank mounting tab causing a fuel leak.

What should you do?

We strongly recommend that you stop using your lawn mower until the fuel tank has been replaced. If you need assistance, please see a member of this dealership's staff or any authorized Honda Power Equipment dealer for assistance. If you need additional assistance that this dealer is unable to provide, you may contact American Honda Customer Relations at (888) 888-3139.

In cooperation with the Consumer Product Safety Commission and California Air Resources Board

PTB53992 (2007.09)