

American Honda Motor Co., Inc.

# **SAFETY AND EMISSIONS** **RECALL NOTICE**

## **EB2800i • EG2800i Generators** **CARBURETOR FUEL LEAK**

Check below to see if your generator is affected by this recall.



Serial Number

Affected Model	Starting Serial Number	Ending Serial Number
EB2800i	EAAA-1000037	EAAA-1015421
EG2800i	EABA-2000047	EABA-2020152


Units previously inspected/repared are no longer part of this recall.

They can be identified by one of the following:



A "blue dot" located on the carton.

A "black dot" located on the QR label or a "7EL" label below the ground wire.



### ***What is the problem?***

Due to a manufacturing error, the carburetor float chamber may not be installed correctly, and can leak fuel. If gasoline or gasoline vapors leak, a fire or explosion could occur.

A fuel leak caused by this manufacturing error is typically noticed by a strong smell of fuel before, during, or after operation, or if fuel is seen leaking underneath the generator. Generators that exhibit any of these symptoms are usually new units with low hours of run time.

### ***What should you do?***

If you own an EB2800i or EG2800i generator, you will need to check to see if the serial number is within the affected serial number range. If it is within the affected range, stop using your generator until it has been inspected by an authorized Honda dealer. Also:

- If your generator was registered with American Honda, you will receive a letter.
- If your generator was not registered with American Honda, contact your Honda Power Equipment servicing dealer.

If you need assistance locating a servicing dealer, please visit our website: [www.PowerEquipment.Honda.com](http://www.PowerEquipment.Honda.com), or call us at our recall line (888) 888-3139.

In cooperation with the U.S. Consumer Product Safety Commission