

American Honda Motor Co., Inc.

# **PRODUCT UPDATE NOTICE**


**HSS724AAW • HSS724AAT • HSS928AAT**  
**Snow Blowers**

## **SLOW GROUND SPEED**

Check to see if your snow blower is affected by this product update.

### ***What is the problem?***

While self-propelling the snow blower under light load conditions, such as during transport, the ground speed may slow/reduce (as much as 50%). The speed increases when additional load is applied.



### ***Affected Serial Numbers***

To find out if your snow blower is affected by this Product Update, see the backside of this page.

### ***What should you do?***

Please contact your Honda Power Equipment servicing dealer to make arrangements to have your HSS724AAW, HSS724AAT, or HSS928AAT snow blower repaired. The dealer will replace the hydrostatic transmission at no charge to you while the snow blower is still under warranty. American Honda will provide pickup and delivery assistance to customers for this repair.

If you need assistance locating a servicing Honda Power Equipment dealer, please visit our website: [PowerEquipment.Honda.com](http://PowerEquipment.Honda.com) or call our customer service line at (888) 888-3139.

**AFFECTED UNITS**

MODEL	FRAME SERIAL NUMBER				
HSS724AAW	SABA-1000015 through SABA-1000516				
HSS724AAT	SABA-1000015 through SABA-1000516				
HSS928AAT	SADA-1000022 through SADA-1000741				
<b>Plus the additional serial numbers shown below</b>					
HSS928AAT	SADA-1001804	SADA-1001850	SADA-1001890	SADA-1001988	SADA-1002041
		SADA-1001851		SADA-1001989	SADA-1002042
	SADA-1001806	SADA-1001852	SADA-1001892	SADA-1001990	SADA-1002043
		SADA-1001853		SADA-1001991	SADA-1002044
	SADA-1001815	SADA-1001854	SADA-1001934	SADA-1001992	SADA-1002045
		SADA-1001855	SADA-1001935	SADA-1001993	SADA-1002046
	SADA-1001821			SADA-1001994	
		SADA-1001858	SADA-1001945	SADA-1001995	SADA-1002048
	SADA-1001823			SADA-1001996	SADA-1002049
	SADA-1001824	SADA-1001861	SADA-1001948	SADA-1001997	SADA-1002050
	SADA-1001825	SADA-1001862	SADA-1001949	SADA-1001998	
	SADA-1001826			SADA-1001999	SADA-1002052
	SADA-1001827	SADA-1001864	SADA-1001962		SADA-1002053
	SADA-1001828	SADA-1001865	SADA-1001963	SADA-1002001	SADA-1002054
	SADA-1001829	SADA-1001866	SADA-1001964	SADA-1002002	SADA-1002055
	SADA-1001830		SADA-1001965	SADA-1002003	SADA-1002056
	SADA-1001831	SADA-1001868	SADA-1001967	SADA-1002004	SADA-1002057
	SADA-1001832		SADA-1001968	SADA-1002005	SADA-1002058
	SADA-1001833	SADA-1001870	SADA-1001969	SADA-1002006	SADA-1002059
	SADA-1001834	SADA-1001871	SADA-1001970	SADA-1002007	SADA-1002060
		SADA-1001872	SADA-1001971	SADA-1002008	SADA-1002061
	SADA-1001836			SADA-1002009	SADA-1002062
	SADA-1001837	SADA-1001874	SADA-1001973	SADA-1002010	SADA-1002063
	SADA-1001838		SADA-1001974		SADA-1002064
	SADA-1001839	SADA-1001876	SADA-1001975	SADA-1002013	
	SADA-1001840			SADA-1002014	SADA-1002067
		SADA-1001878	SADA-1001977		
	SADA-1001842		SADA-1001978	SADA-1002018	SADA-1002071
		SADA-1001880	SADA-1001979		
	SADA-1001844	SADA-1001881	SADA-1001980	SADA-1002020	SADA-1002074
	SADA-1001845		SADA-1001981		
	SADA-1001846	SADA-1001883	SADA-1001982	SADA-1002022	
SADA-1001847	SADA-1001884	SADA-1001983			
SADA-1001848	SADA-1001885	SADA-1001984	SADA-1002039		
	SADA-1001886	SADA-1001985			
	SADA-1001887	SADA-1001986			
	SADA-1001888	SADA-1001987			