

American Honda Motor Co., Inc.

SAFETY RECALL NOTICE

HS724, HS928, HS1132 Snowblowers


FUEL TANK JOINT

Check below to see if your snowblower is affected by this recall.

HS724, HS928, HS1132

Frame Serial Number Range

HS724	SZBE-1037913 ~ 1046577
HS928	SZAS-1151080 ~ 1169012
HS1132	SZBF-1018734 ~ 1025998



⚠ WARNING

Gasoline is highly flammable and explosive. You can be burned or seriously injured if gasoline from a leaking fuel tank is ignited. If the fuel tank is leaking:

- Move the snowblower away from any source of ignition.
- Drain the fuel tank into an approved container.
- Do not use the snowblower until it has been repaired.

Consumers should immediately stop using the recalled snowblower and contact a Honda Power Equipment dealer for a free repair.

What is the problem?

Affected snowblowers may, over time, begin seeping fuel from the fuel tank joint O-ring, located on the underside of the fuel tank. If the seepage becomes severe, fuel will begin to drip, increasing the risk of a fire.

What should you do?

Stop using any snowblower within the affected serial number range until the fuel tank joint and O-ring have been replaced. Please contact a servicing Honda Power Equipment dealer to make an appointment to have your snowblower repaired free of charge. If you need assistance locating a servicing dealer, please visit our website: www.HondaPowerEquipment.com, or call us at our recall line (888) 888-3139.

In cooperation with the U.S. Consumer Product Safety Commission