

SAFETY RECALL NOTICE

EU7000isAT Generators

INCORRECT CARTON HAZARD LABELS

Check below to see if your generator is affected by this recall.



Serial Number
(inside cover)

Affected Model	Starting Serial Number	Ending Serial Number
EU7000isAT	EEJD-1000001	EEJD-1006288

Units previously inspected/repaired are no longer part of this recall.

They can be identified as follows:

EU7000is
AT
R280 RED
EEJD- 1000001

Boxed generators are identified by a "green dot" located on the carton.

Repaired generators are identified by a "black dot" located on the UPC label on the fuel tank.

Consumers should contact a Honda Power Equipment dealer or Honda Power Equipment to obtain correct carton labels, as described below.

What is the problem?

Due to a printing error, the carton does not display the required hazard labels. The English hazard label was missing from the carton and the Spanish hazard label was not correctly translated.

Customer safety is very important to Honda. Follow the instructions in the owner's manual and on the generator hazard labels to avoid carbon monoxide (CO) poisoning and other safety hazards.

What should you do?

If you received your EU7000isAT generator with its shipping carton and the carton does not have hazard labels that match those shown to the right on the longer panels and carton top, please contact a servicing Honda Power Equipment dealer to obtain replacement labels. Alternatively, please call our recall line at (888) 888-3139 to request that replacement labels be sent directly to you. If you need assistance locating a servicing dealer, please visit our website: www.PowerEquipment.Honda.com, or call us at our recall line (888) 888-3139.



In cooperation with the U.S. Consumer Product Safety Commission