

American Honda Motor Co., Inc.

SAFETY RECALL NOTICE

EU7000isAT Generators

REAR PIPE FAILURE & OWNER'S MANUAL ERROR


Check below to see if your generator is affected by these recalls.



Recall	Affected Models	Starting Serial Number	Ending Serial Number
Rear Pipe	EU7000isAT	EEJD-1000001	EEJD-1006288
Owner's Manual	EU7000isAT	EEJD-1000892	EEJD-1006288

Units previously inspected/repared are no longer part of this recall.

They can be identified as follows:



Consumers should immediately stop using the recalled generator and contact a Honda Power Equipment dealer to have it inspected/repared free of charge.

What are the problems?

Due to a manufacturing defect, the rear pipe on affected units may have insufficient welds and break while lifting or transporting the generator. This poses a potential safety hazard to the operator.

Due to an assembly error, the owner's manual may have duplicate or missing pages. An incomplete owner's manual may not include appropriate safety information.

What should you do?

Stop using any generator within the affected serial number range until it has been repaired. Please contact a servicing Honda Power Equipment dealer to make an appointment to have your generator inspected and if necessary repaired, free of charge. If you need assistance locating a servicing dealer, please visit our website: www.PowerEquipment.Honda.com, or call us at our recall line (888) 888-3139.

In cooperation with the U.S. Consumer Product Safety Commission