

PRODUCT SAFETY RECALL
PTO Arm:
Issued January 1998

MODEL: H2013 Honda Lawn Tractor

SERIAL #'s MZBF-6000001-6107254

PROBLEM: Honda has received some reports of the PTO arm failure on some lawn tractors. If the PTO arm breaks, you may not be able to engage or disengage a PTO-driven attachment. On this unit the PTO driven attachments are a mower deck or snow thrower. If the PTO fails to disengage, the mower blades or snow thrower auger would continue to rotate even when the PTO lever is in the OFF position. Contact with a rotating blades or auger could cause severe personal injury.

WHAT TO DO: Please contact a servicing Honda lawn and garden dealer to make an appointment to have your tractor repaired. To find the nearest Honda authorized dealer you may check our dealer locator on our web site: www.hondapowerequipment.com or call toll free 1-888-888-3139.