

PRODUCT SAFETY RECALL

Rear Axle:

Issued August 1988

- MODEL:** HT-R3009 Honda Riding Mower
- SERIAL #'** MA1T-5000033-5018092
- PROBLEM:** A recall campaign has been initiated to install rear axle retainers to prevent separation of the rear axle shafts from the differential. This rear axle separation could cause a loss of power to the rear wheels and all braking ability.
- WHAT TO DO:** Please contact a servicing Honda lawn and garden dealer to make an appointment to have your riding mower repaired. To find the nearest Honda authorized dealer you may check our dealer locator on our web site: www.hondapowerequipment.com or call toll free 888-888-3139.