

American Honda Motor Co., Inc.

SAFETY RECALL NOTICE

HRR2169VLA and HRX2174VLA ELECTRIC START LAWN MOWERS ENGINE STOP SWITCH



MEETS CPSC BLADE SAFETY REQUIREMENTS.
CONFORMS TO ANSI B 71.1-SAFETY STANDARD
MODEL: HRR2169VLA
SERIAL NO: MZCG — XXXXXXX
American Honda Motor Co., Inc.
Alpharetta, GA 30005-8847

MEETS CPSC BLADE SAFETY REQUIREMENTS.
CONFORMS TO ANSI B 71.1-SAFETY STANDARD
MODEL: HRX2174VLA
SERIAL NO: MAGA — XXXXXXX
American Honda Motor Co., Inc.
Alpharetta, GA 30005-8847



Check to see if your lawn mower is affected by this recall.

Model	Affected Serial Number Range
HRR2169VLA	MZCG-8764914 ~ MZCG-8824353

Model	Affected Serial Number Range
HRX2174VLA	MAGA-2255148 ~ MAGA-2260227

What is the problem?

- The engine stop switch may become inoperative allowing the lawn mower engine to continue to run after the flywheel brake lever is released
- Because the blades continue to rotate, this poses a potential safety hazard to the operator or a bystander

What should you do?

- Check to see if the model and serial number of your lawn mower are within the affected range
- Do not use the lawn mower until it has been repaired
- Contact an authorized Honda Power Equipment servicing dealer to make an appointment to have the flywheel brake assembly on your lawn mower replaced free of charge

Affected units that have already been repaired are no longer part of this recall and can be identified as follows:



Round green sticker on the carton.

Punch mark next to the engine serial number.



If you need assistance locating an authorized Honda Power Equipment servicing dealer:

Website: www.powerequipment.honda.com

Phone: (888) 888-3139.

This recall is being conducted in cooperation with the U.S. Consumer Product Safety Commission.