

PRODUCT SAFETY RECALL
Roto-stop® Brake Plate Failure
Issued July 2003

MODEL: Honda Harmony Lawn mower HRB216TXA, HRB216HXA

SERIAL #s: MAAA-1005910-1047430 (TXA)
MAAA-1005790-1055830 (HXA)

PROBLEM: If the lawn mower strikes an object with sufficient force, the crankshaft could bend. Vibration created by a bent crankshaft may eventually result in fatigue failure of the Roto-stop® blade brake control assembly, allowing the cutting blade to continue rotating after the blade control lever is released.

*Crankshafts can bend when the lawnmower strikes a solid object in the lawn such as a rock, bone, tree branch, tree stump, water pipe, etc. Contact or impact damage is not caused by a manufacturing defect. Consequently, the repair is the owner's responsibility.

WHAT TO DO: Please contact your servicing Honda lawn and garden dealer to make an appointment to have your lawnmower repaired with the improved Roto-stop® brake plate at no charge. To find the nearest Honda authorized dealer you may check our dealer locator on our web site: www.hondapowerequipment.com or call toll free 1-888-888-3139.