

American Honda Motor Co., Inc.


SAFETY RECALL NOTICE

BF15D • BFP15D • BF20D • BFP20D Outboard Motors

FUEL CHAMBER LEAK

Check below to see if your outboard is affected by this recall.

BF15D • BFP15D
BF20D • BFP20D



Affected Serial Numbers

BALJ-1000001~1402293

BAMJ-1000001~1403159

⚠ WARNING

The fuel chamber could fail without warning, releasing fuel into the engine compartment.

Starting and running the engine could cause the fuel and fuel vapors to ignite, causing serious injury.

Do not use your outboard until the fuel chamber has been replaced.

What is the problem?

The fuel chamber may crack and leak fuel. This leakage is due to exposure to water elements and stress resulting from the method used to install the fuel chamber.

What should you do?

Stop using your outboard motor until the fuel chamber has been replaced.

Please contact a servicing Honda Marine dealer to make an appointment to have your BF15D, BFP15D, BF20D, or BFP20D outboard repaired. The dealer will replace the fuel chamber, free of charge. Transportation of the outboard to and from the dealer is the responsibility of the owner.

If you need assistance locating a servicing Honda Marine dealer, please visit our website: www.honda-marine.com, or contact us at (888) 888-3139.

In cooperation with the U.S. Coast Guard