


SAFETY RECALL NOTICE

HSS724AAT • HSS724AAW Snow Blowers OWNER'S MANUAL PRINTING ERROR

Check below to see if your snow blower is affected by this recall.



Affected Models	Starting Serial Number	Ending Serial Number
HSS724AAT	SABA-1000231	SABA-1000516
HSS724AAW	SABA-1000015	SABA-1000217

What are the problems?

Due to a printing error, Safety Messages, the Introduction, and an undersized Registration Card appear on a folded, loose-leaf sheet inserted in the owner's manual. This may cause an owner to lose important safety information, while the Registration Card does not meet U.S. Postal Service size requirements.

What should you do?

A properly printed owner's manual and registration card is available to correct this error. The replacement owner's manual can be identified by the 00X31V45 A040 part number located at the bottom left corner of the front cover. Owner's manuals and registration cards are being provided by American Honda Motor Co., Inc. free of charge. Contact Honda Service Publications at 770-497-6400, option 4.

INTRO, SAFETY MESSAGES, AND REG CARD FOLDED AND INSERTED INTO MANUAL

PART NUMBER OF INCORRECT OWNERS MANUAL 00X31V45 A000

PART NUMBER OF CORRECTED OWNERS MANUAL 00X31V45 A040

CORRECTED PRODUCT REGISTRATION CARD INSERTED IN MANUAL

00X31V45 A040