

PRODUCT SAFETY RECALL
Hitch Rod Failure:
Issued December 1995

MODEL: SLK7000 SULKY

SERIAL #'s All units

PROBLEM: If the hitch rod fails, the floor pan will drop on the control rod.
This may result in injury to the operator.

WHAT TO DO: Discontinue use of SLK7000 Sulky and take to your nearest
Honda authorized dealer. To find the nearest Honda dealer you may check our dealer
locator on our web site: www.hondapowerequipment.com or call toll free 1-800-426-
7701.